
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary ————————————————————————————————————								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-034	Smoke	8/18/2008	ADS/TM	S13WW_010MH	Dry	Yes	1,708.55	



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary ————————————————————————————————————								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-034	Smoke	8/18/2008	ADS/TM	S13WW_010MH	Dry	Yes	1,708.55	

ted Pipes ——				
Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13WW_010G1	S13WW_010MH	S13WW_004MH	353.4367	8
S13WW_001G1	S13WW_001MH	S13WW_010MH	307.6093	8
S13WW_004G1	S13WW_004MH	S11UU_009MH	328.0791	8
S11UU_009G1	S11UU_009MH	S11UU_006MH	213.8371	8
S13YY_022G1	S13YY_022MH	S13YY_012MH	24.96392	8
S13WW_016G1	S13WW_016DE	S13YY_012MH	427.3646	8
S13YY_005G1	S13YY_005MH	S13YY_022MH	53.25573	8

Observations & Photos

Obs_ID S1028-034-OB01 **Address** 3621 Rosedale Road

Status Private **Source** Cleanout

Location Yard - front **Nearest MH** S13YY_012MH

Comments Smoke from cleanout in front yard. 3621 Rosedale Rd.



Picture \S1028-034-OB01-P01.jpg

Comments Front of house, 3621 Rosedale

Rd.

Obs_ID S1028-034-OB02 **Address** 3501 Rosedale Road

Status Private **Source** Cleanout

Location Yard - side **Nearest MH** S13WW_004MH

Comments Smoke from cleanout in side yard. 3501

Rosedale Rd.



Picture \S1028-034-OB02-P01.jpg

Comments Side of house, 3501 Rosedale Rd.

Smoke and Dye Testing Summary

High Level Sewershed

_	_	
Run	Summary	

Kun Summury									
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length		
S1028-034	Smoke	8/18/2008	ADS/TM	S13WW_010MH	Dry	Yes	1,708.55	_	

Obs_ID S1028-034-OB03 Address 3501 Rosedale Road **Status** Public Status Private Source Service Lateral Source Cleanout Location Sidewalk Location Yard - front Nearest MH S13WW_004MH

Smoke from service lateral in side yard. Hole **Comments**

next to sidewalk 7' from road. 3501 Rosedale



Picture \S1028-034-OB03-P01.jpg

Comments Side of house, 3501 Rosedale Rd.

Obs_ID S1028-034-OB05 Address 3050 Liberty Heights Ave.

Status Public Source Catch Basin Location Curb

Nearest MH S11UU_006MH

Smoke from catch basin. 3050 Liberty Heights Comments



Picture \S1028-034-OB05-P01.jpg

Front of house, 3050 Liberty Comments

Heights Ave.

Obs_ID S1028-034-OB04 Address 3403 Rosedale Road

Nearest MH S11UU_009MH

Smoke from cleanout in front yard. 3403

Rosedale Rd.



Picture \S1028-034-OB04-P01.jpg

Front of house, 3403 Rosedale Comments

Obs_ID S1028-034-OB06

Address 3050 Liberty Heights Ave

Status **Public** Source Main Sewer Location Curb

Nearest MH S11UU_006MH

Smoke from main line sewer in front of Comments

property. 3050 Liberty Heights Ave.



Picture \S1028-034-OB06-P01.jpg

Front of house, 3050 Liberty Comments

Heights Ave.



Tuesday, February 10, 2009

Page 3 of 3